

Linia trasowania 3				
Numer	Współrzędna N początku	Współrzędna S początku	Współrzędna N końca	Współrzędna S końca
L38	5503691.1032	4546854.6978	5503536.9352	4546886.9788
C27	5503536.9352	4546886.9788	5503531.9067	4546888.0995
L37	5503531.9067	4546888.0995	5503279.7931	4546947.7069
C26	5503279.7931	4546947.7069	5503279.0673	4546947.8770
L36	5503279.0673	4546947.8770	5502928.3158	4547029.4261
C25	5502928.3158	4547029.4261	5502905.4487	4547036.2027
L35	5502905.4487	4547036.2027	5502879.1599	4547045.7322
C24	5502879.1599	4547045.7322	5502855.8859	4547052.6029
L34	5502855.8859	4547052.6029	5502789.7550	4547067.8327
C23	5502789.7550	4547067.8327	5502788.7931	4547068.0567
L33	5502788.7931	4547068.0567	5502705.5654	4547087.6572
C22	5502705.5654	4547087.6572	5502701.6304	4547088.5422
L32	5502701.6304	4547088.5422	5502605.0852	4547109.2334
C21	5502605.0852	4547109.2334	5502598.9738	4547110.6437
L31	5502598.9738	4547110.6437	5502498.6231	4547135.4656
C20	5502498.6231	4547135.4656	5502496.5275	4547135.9720
L30	5502496.5275	4547135.9720	5502331.3745	4547174.9385
C19	5502331.3745	4547174.9385	5502331.1925	4547174.9815
L29	5502331.1925	4547174.9815	5502249.9300	4547194.2350